

FALLS OF GROUND CAN KILL

Falls of ground are the biggest cause of deaths and injuries in mining.

Falls of ground can be prevented.




Protect yourself and those around you.

Always




Conduct thorough entry examinations and 'make safe' all working places before work begins



Install temporary and permanent support according to mine-specific standards



When in doubt, tell your supervisor about your concerns



Where a working place cannot be made safe, you have the right to withdraw from the working area